



Mobile Phone Support List

Last Update: July 2009

Mobile Phone Type	Smart Phone		
Multicam Version	v7.01 ~ v8.02	v8.10 ~ v8.20	v8.20 ~ v8.32
Mobile Phone OS	Windows Mobile 2003 Window Mobile 5.0	Windows Mobile 2003 Window Mobile 5.0 Window Mobile 6.0 or later	Window Mobile 6.0 or later
Mobile Application Required	MSView	MSViewV2	MSViewV3
Ports Required To connect to DVR	80 (HTTP)	8866 (Live) 5511 (Playback) 4550 (Command) 5550 (Data)	8866 (Live) 5511 (Playback) 4550 (Command) 5550 (Data)
Ports Required To connect to GV-IP Devices	N/A	10000 (Live) 5552 (Playback)	10000 (Live) 5552 (Playback)
Tested Compatible Phone Models (with tested OS or wireless carrier if applicable)	Mio 8390 (WM 2003)	Dopod 595 HTC Touch (WM 6.0 Professional) Mio 8390 (WM 2003) Motorola MPX 220 Motorola Q (Verizon Wireless)	HTC Touch (WM 6.0 Professional)

Mobile Phone Type	PDA	
Multicam Version	v5.21 ~ v8.10	v8.10 ~ v8.32
Mobile Phone OS	Windows Mobile 2002 Windows Mobile 2003 Window Mobile 5.0	Window Mobile 5.0 Window Mobile 6.0 or later
Mobile Application Required	Gview	GViewV2
Ports Required To connect to DVR	80 (HTTP) 4550 (Command) 5550 (Data)	8866 (Live) 5511 (Playback) 4550 (Command) 5550 (Data)
Ports Required To connect to GV-IP Devices	10000 (Live) 5552 (Playback)	10000 (Live) 5552 (Playback)
Tested Compatible Phone Models (with tested OS or wireless carrier if applicable)	Dopod 828 Dopod 838 Pro Dopod 900 Dopod CHT 9000 HP IPAQ H3900 HP IPAQ PE2050A HTC Touch (WM 6.0 Professional) Toshiba E740	Dopod 828 Dopod 838 Pro Dopod 900 Dopod CHT 9000 HP IPAQ H3900 HP IPAQ PE2050A HTC Touch (WM 6.0 Professional) Toshiba E740

Note 1: * May require non-default ports, default ports as shown may be blocked by wireless carrier

Note 2: v8.2 and v8.3 Mobile applications are not backward or forward compatible.

In order to view v8.3 Multicam, appropriate mobile applications must be installed from v8.3 installation disk.

Mobile Phone Support List

Last Update: July 2009

Mobile Phone Type	Symbian		
Multicam Version	v7.00 ~ v8.12	v8.1 ~ v8.32	v8.1 ~ v8.32
Mobile Phone OS	Symbian 7.0 or later	Symbian 7.0 or later	Nokia S60 2nd and 3rd
Mobile Application Required	SSView	SSViewV2	SSViewV3
Ports Required To connect to DVR	80 (HTTP)	8866 (Live)	8866 (Live) 5511 (Playback) 4550 (Command) 5550 (Data)
Ports Required To connect to GV-IP Devices	N/A	N/A	10000 (Live) 5552 (Playback)
Tested Compatible Phone Models (with tested OS or wireless carrier if applicable)	Motorola E1070 Nokia 6680 Nokia N73 Sony Ericsson P900i Sony Ericsson P990 Sony Ericsson Z800	Motorola E1070 Nokia 6680 Nokia N73	Nokia E60 Nokia E61 Nokia N73 Nokia N95

Mobile Phone Type	BlackBerry	IPhone
Multicam Version	v8.3 ~ v8.32	v8.31 ~ v8.32
Mobile Phone OS	N/A	N/A
Mobile Application Required	BBView	iView
Ports Required To connect to DVR	80 (HTTP) 8866 (Live) 4550 (Command) 5550 (Data)	80 (HTTP) 8866 (Live) 4550 (Command) 5550 (Data)
Ports Required To connect to GV-IP Devices	10000 (Live)	10000 (Live)
Tested Compatible Phone Models (with tested OS or wireless carrier if applicable)	Blackberry 8300 (AT&T)* Blackberry 8320 (T-Mobile) Blackberry 8330 (Verizon)*	IPhone (AT&T) IPhone (T-Mobile)

Note 1: * May require non-default ports, default ports as shown may be blocked by wireless carrier

Note 2: v8.2 and v8.3 Mobile applications are not backward or forward compatible.

In order to view v8.3 Multicam, appropriate mobile applications must be installed from v8.3 installation disk.